Chapter

Solid Problem Three

In this chapter, you will learn the following to World Class standards:

- Sketch of Solid Problem Three
- Starting a 3D Part Drawing
- Drawing a Closed Polyline Shape to be Extruded
- Adding Circles to be Extruded
- Rotating a 3D Solid Using the Rotate Command
- Extruding a Solid from Closed Polylines and Circles
- Moving a Solid within the Master Solid
- Union Two Solids
- Subtracting Two Solids from the Master Solid
- Placing an Curved Edge on a Solid Using the Fillet Tool Moving
- Saving the Solid Problem

Sketch of Solid Problem Three

You start the third solids problem with a rough sketch showing the dimensions of each detail. This part is symmetrical across one line which you can call the y-axis. In this exercise, a strategy you will continue to use is to draw closed Polylines that contain the most complex shape of the component and then use simple geometric solids to add or subtract details. In problem three, the solid contains an inverted "c" that will be formed into a Polyline shape along with a second rectangular Polyline contour, and you will place two circles in the middle of the second shape. After extruding the Polylines and Circles, we will use the Union command to join the two shapes together and you will subtract the two circles to make the hole and counterbore. You will fillet a curve in two places as shown in your sketch in Figure 4.1.



Figure 4.1 – Problem Three Sketch

Remember, when you receive a sketch from a professional, you need to practice to quickly identify the different shapes and decide how to proceed with the solid exercise. You can see rather quickly that problem three has different heights so separate each extrusion or part that is made and bring them together. This problem will help you address solid parts where there are different complexities and thicknesses. All ten drills in the Fundamentals of 3D Drawing textbook will give you those repetitive maneuvers, which will make you successful in 3D modeling.

Starting a 3D Part Drawing

In Problem Three, you will begin the 3D drawing by selecting the Mechanical template. In Figure 4.2, the window "Select template" window is loaded by selecting the New tool on the Quick Access toolbar. Scroll down the list and select Mechanical.dwt. A new drawing file will open that contains the system variables and layer definitions which you will use later in Paper Space to finish the drawing.

Select template				×
Look in:	🕕 Template	- 두 😥	🍳 🗙 🅵 🛛 <u>V</u> iews 👻	Too <u>l</u> s 👻
Æ	Name	Date modified	Preview	
~>>	PTWTemplates	12/28/2008 2:23 PN		
History	SheetSets	12/28/2008 2:23 PN		
	own acad	1/19/2008 5:36 PM		
	own acad3D	1/19/2008 5:35 PM		
Documents	acad -Named Plot Styles	1/19/2008 5:35 PM		
I	acad -Named Plot Styl			
	acadiso	1/19/2008 5:45 PM		
Favorites	acadiso3D	1/19/2008 5:44 PM		
	acadISO -Named Plot			
	acadISO -Named Plot			
Desktop	own Architectural	1/7/2009 9:54 PM		
- 39	Mechanical	1/2/2009 1:47 PM		
	iown Metric	1/2/2009 3:55 PM		
FTP	•	P		
-39				
1	File name: Mechanical		▼ _)pen 🗸 🔻
Buzzsaw	Files of type: Drawing Templat	te (*.dwt)	_	Cancel

Figure 4.2 – Starting the Drawing Using the Mechanical Template

Drawing a Closed Polyline Shape to be Extruded

On the Draw panel under the Home tab, select the Polyline tool and specify a start point in the lower left hand corner of the graphical display. In Figure 4.3, you can see the actual continuous line of data you need to specify at the command line.

```
Command: _pline
Specify start point:
Current line-width is 0.0000
Specify next point or [Arc/Halfwidth/Length/Undo/Width]: 2.75
Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: 3
Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: 2.75
Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: 0.75
Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: 2
Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: 1.5
Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: 2
Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: 1.5
Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: 2
```

Figure 4.3 – The Polyline Text from the Command Line

With the Ortho mode "on", draw a 2.75 unit line to the right, a 3.0 line up, a 2.75 line to the left, a 0.75 line downward, a 2.0 line to the right, a 1.5 line downward, a 2.0 to the left and then type "C" to close the Polyline. A closed entity will appear in the graphical display as shown in Figure 4.4. Select the Zoom tool on the Status bar and draw a window around the closed Polyline to have the part fill the monitor.









Command: **_pline** Specify start point: Current line-width is 0.0000 Specify next point or [Arc/Halfwidth/Length/Undo/Width]: **2** Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: **3** Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: **2** Specify next point or [Arc/Close/Halfwidth/Length/Undo/Width]: **2**

Figure 4.6 – The Polyline Text from the Command Line

With the Ortho mode still "on", press Enter to repeat the Polyline command and select the lower right end of the first Polyline as your starting point. Draw a **2.0** unit line to the right, a **3.0** line up, a **2.0** line to the left and then type "C" to close the Polyline. A closed entity will appear in the graphical display as shown in Figure 4.5. Select the Zoom tool on the Standard toolbar to have the box fill the monitor, so you can proceed to the next step in the drawing process.

Adding Circles to be Extruded

Next, select the Center, Diameter command on the Draw panel of the Home tab as shown in figure 4.7. Place the mouse aperture midway up the vertical line as shown in Figure 4.8 and a Midpoint Osnap symbol (triangle) will appear in the middle of the line. Select the center point of the circle by selecting with the left mouse button and then type "1" when the command line prompts you to "specify diameter of circle". Repeat the Center, Radius command by pressing Enter, and place the **1.25** diameter circle outside the 1-diameter circle having them sharing the same center points. There will be two concentric circles as shown in Figure 4.9.



\$



Figure 4.7 – Circle on the Draw Panel



Figure 4.8 – Midpoint on the Polyline



Figure 4.9 – Drawing Two Circles

Figure 4.10 – Moving Two Circles

Next, you need to move the two circles one inch to the left, so select the Move tool on the Modify panel. Once you choose the Move command, you will be prompted to "Select **Objects**". You can do this by placing the pick box that now has replaced the aperture cursor on each circle and select both entities. The command line will respond with "2 found", so just press Enter to go the second part of the command. Next, you need to "specify base point or displacement" on the graphical display. Pick your base point anywhere on the graphical display. Push the mouse to the left to direct the circles and type "1". Both circles will be 1 inch to the left of the right vertical line segment as shown in Figure 4.10.

Rotating a 3D Solid Using the Rotate Command

On the View panel under the Home tab, select the Southwest Isometric View tool which allows you to see the part on the XY plane and the vertical Z-axis will rise from the level surface. (See Figure 4.11). To rotate the solid in the XY plane, select the regular Rotate command on the Modify panel. Select the Rotate command on the Modify panel and pick the solid. The selected entity will be dotted and to continue with the command, press **Enter** to select the base point of rotation. Select any point at the base of the solid with the left mouse button and then type **90** for the degrees of counter clockwise rotation to finish this detail (See Figure 4.12).



Figure 4.11 – Southwest Isometric View

Figure 4.12 – Rotating 90 Degrees

Extruding a Solid from Closed Polylines and Circles

Only closed entities like Polylines and Circles can be extruded using this very powerful tool on the Modeling panel of the Home tab. If a there is even a minute space in the entity a warning will appear on the command line that you are "**unable to extrude the selected object.**" If you use an attention to detail in your 3D Computer Aided Design work, you can create the most complex shapes with the extrusion instrument.



Figure 4.13 – Extrude the Inverted "C"

Select the Extrude tool on the Modeling panel and the command line on the AutoCAD application will prompt you to "select objects". Pick the Closed Polyline that looks like an inverted "C" anywhere on the peripheral line and the command line will return with "1 found". Press Enter to specify the height or path of the solid. You can type "P" for Path and choose an entity to extrude the shape along, but you will not want that option for problem three. You will type "2" for the height of the extrusion and for the angle of taper you will Enter to accept the zero degree default. A more complex 3D solid will appear in the graphical display as shown in Figure 4.13.



For the second set of solids, choose the Extrude tool on the Modeling panel and the command line will prompt you to "select objects". Pick the Closed Polyline that looks like a rectangle anywhere on the peripheral line and the smaller circle and the command line will return with "2 found". Press Enter to specify the height or path of the solid. You will type "0.75" for the height of the extrusion and for the angle of taper you will Enter to accept the zero degree default. A solid box will appear with a solid cylinder in the graphical display as shown in Figure 4.14.

Figure 4.14 – Extrude Two Solids

Notice that you are able to extrude more than one entity at a time to create separate solids. This procedure comes in handy when making holes in plates when there are already circles available for extrusion.



Figure 4.15 – Extrude the Second Cylinder

For the third solid, pick the Extrude tool on the Modeling panel and the command line will prompt you to "**select objects**". Pick the larger circle anywhere on the peripheral line and the command line will return with "**1 found**". Press **Enter** to specify the height or path of the solid. You will type "**0.25**" for the height of the extrusion and for the angle of taper you will hit **Enter** to accept the zero degree default. A solid cylinder in the graphical display as shown in Figure 4.15. Now you need to move the 1.25 diameter cylinder into place as shown in your sketch.

Moving a Solid onto the Master Solid

Remember, the Move command is actually a three dimensional function and you can use the tool to relocate any entity to another point (X,Y,Z) in Model Space.



To move the 1.25 diameter cylinder, you select the Move tool on the Modify panel. Once you choose the Move command, the prompt will be "Select Objects". Pick the 1.25 cylinder and the command line will respond with "1 found", so just press Enter to go the second part of the command. Next, you need to "specify base point or displacement" on the graphical display. Pick your base point with the Center Osnap selecting the top of the 1.25 cylinder. The "second point of displacement" is the center point of the 1.0 cylinder. Pick the second point using the Center Osnap and the 1.25 cylinder will move as shown in Figure 4.16.

Figure 4.16 – Moving a Cylinder

Union Two Solids

For the next modification of a 3D solid shape in AutoCAD, you need to use the Boolean command, Union. With the Union command, you will join one shape or more together.



To add two solid to another one, select the Union tool on the Solid Editing panel. Then the AutoCAD program will prompt you with "Select objects". Select the inverted "C" solid and the system will respond with "1 found". Pick the rectangular solid and the software application will counter with "1 found". Hit Enter and now both solids become as one entity, as shown in Figure 4.17. You can see in the graphical display that the tessellation lines outlining both boxes and were crossing each other in the corner of the "L" shape are now missing. Select the solid with one pick of the mouse and the entire solid will become highlighted.

ന

Figure 4.17 – Union Two Solids

Subtracting a 3D Solid from Another Solid

To remove the smaller solid boxes from the master solid, select the Subtract tool on the Solid Editing panel.



The AutoCAD program will prompt you with "Select solids and regions to subtract from". Select the larger master solid and the system will respond with "1 found". You need to hit Enter to proceed to the next step, which is "Select solids and regions to subtract". Pick the two cylinders and the software application will counter with "2 found". Hit Enter and a region exactly the shape of the two cylinders is missing from the larger one as shown in Figure 4.18. This technique to enhance the detail of a solid entity by removing a part of the feature is commonplace in the world of 3D design.

Figure 4.18 – Subtract the Two Cylinders

Placing a Curved Edge on a Solid Using the Fillet Tool

To place a fillet or curve on two converging straight lines in the Fundamentals of 2D Drawing, you need to select both lines to identify the position of the radius. When placing a three dimensional curve on a solid, you pick the straight line on the corner. In this case, the curvature is on the edge of a box in the z-axis.



Select the Fillet tool on the Modify panel. Again, this is a very simple command, because of the movements after picking the tool. Type an "**R**" for radius and then 0.5 for the measurement. Now pick the vertical line on the straight corner and Enter and the line will become dotted. At the prompt, "Select an edge or [Chain/Radius]:" just hit Enter again since you will not be linking the curved surface with any other edge causing a continuous rounded periphery. On the second Enter, the sharp corner becomes a 0.5 curvature. Repeat the process for the other side of problem three and you will have symmetrical fillets. You can actually pick more than one edge to fillet at a time with the same measurement, but on this first attempt, stay with the basics.

Figure 4.19 – Placing Curves on a Solid

Moving the Solid to the Origin Point

To move Problem Three to the drawing origin of 0,0,0 on the x, y and z axis, pick the Move tool on the Modify panel, select the 3D solid, and hit Enter. At the prompt, "specify base point or displacement", select the endpoint shown in Figure 4.19 at the upper left hand side of the Problem Three, which will become the Problem Three insertion point into an assembly drawing. At the "second point of displacement", type 0,0,0 and Enter. Problem Three will move to the new origin point as shown in Figure 4.20. There is more than one way to do many actions in AutoCAD, but the end result of having a part at the origin is important when you wish to insert the solid into an External Referenced Assembly drawing.







Figure 4.20 – Moving the Finished Solid to the Origin

Saving the Solid Problem

To save Problem 3 in your Fundamentals of 3D Drawing Folder, select the Save tool on the Quick Access toolbar. The Save Drawing As window will appear in your graphical display. In the Save In list box, select your drawing folder. At the File Name textbox, type "Problem 3" and press the Save button to save the drawing. (See Figure 4.20)

🏝 Save Drawing	As						×
Save in:	Fundamer Bio problem 1	tals of 3D Drawing		Preview	⊻iews	▼ Toojs	•
Desktop	File <u>n</u> ame:	Update sheet and view thumbna	ils now		~ (<u>S</u> ave	
Buzzsaw	Files of type:	AutoCAD 2007 Drawing (*.dwg)			• (Cancel	

Figure 4.20 – Saving Problem Three

* World Class CAD Challenge 03-03 * - Close this drawing file. Create a New file and draw the twp closed Polylines, extrude and union them. Draw and extrude the two circles, move and subtract them. Add two curve edges on the solid. Move the finished solid to the origin of the drawing. Complete the task in less than 5 minutes. Continue this drill four times, each time completing the drawing under 5 minutes to maintain your World Class ranking.

* World Class CAD Challenge * - Report your best times to World Class CAD at www.worldclasscad.com to obtain your world class ranking.