


DIMENSIONS ON DRAWINGS :


* CHANGING ALL THE DIMENSIONS ON A DRAWING FROM DECIMAL TO FRACTION OR FROM FRACTION TO DECIMAL :

* GO TO BOTTOM RIGHT HAND CORNER, AND PULL MENU SELECTION UP

LEFT CLICK ON "DIMENSION"



* ONCE SELECTED, THEN LEFT CLICK AGAIN AND HOLD DOWN BUTTON TO BOX COMPLETE DRAWING



ONCE BOX IS CREATED



RIGHT CLICK MOUSE

PROPERTIES

DIMENSION PROPERTIES

* SELECT DIMENSION REQUIREMENT

FORMAT

DECIMAL

FRACTION

OK